DORSEY & WHITNEY LLP

MINNEAPOLIS

NEW YORK

SEATTLE

DENVER

WASHINGTON, D.C.

DES MOINES

ANCHORAGE

LONDON

COSTA MESA

PILLSBURY CENTER SOUTH 220 SOUTH SIXTH STREET

MINNEAPOLIS, MINNESOTA 55402-1498

TELEPHONE: (612) 340-2600

FAX: (612) 340-2868

BILLINGS

GREAT FALLS

MISSOULA

BRUSSELS

FARGO

HONG KONG

ROCHESTER

SALT LAKE CITY

VANCOUVER

ROBERT E. CATTANACH 612-340-2873 FAX: 612-340-2807 cattanach.robert@dorseylaw.com

June 20, 2001

Mary McAuliffe U.S. Environmental Protection Agency, Region 5 77 West Jackson Boulevard Chicago, Illinois 60604-3507

RE: Metropolitan Council Supplemental Environmental Project

Dear Mary:

I have enclosed the supplemental information on fabric filter technology you requested. As you recall, the Metropolitan Council ("Met Council") has proposed using fabric filters instead of a dry electrostatic precipitator ("ESP") to accomplish the Supplemental Environmental Project ("SEP") outlined in Appendix C of its Consent Decree with the United States of America. Fabric filters will enhance particulate removal from the Met Wastewater Treatment Plant ("WWTP") incinerator and provide the additional benefit of significantly increased mercury reductions. The estimated cost is expected to be approximately the same for both technologies.

As the attached letter from Met Council's consultant outlines, using fabric filters in the fluidized bed incinerator and air pollution control train will result in better particulate removal efficiencies than the dry ESP because the filter is less sensitive to fluctuations in gas stream conditions, variations in particle size and variations in physical parameters, such as the resistivity of particulate matter. Fabric filters, combined with upstream carbon injection, should be able to provide greater mercury removal than the dry ESP because mercury adsorption can occur in both the reaction chamber and on the fabric filter.

The fabric filter considered for the project is a woven fiberglass material with a polytetrafluoroethylene finish. The finish provides a coating on the filter that improves cleanability and reduces residual dust buildup on the fabric. The total cost for the dry ESP technology is \$2,108,000, compared with \$2,144,000 for the fabric filter technology.

DORSEY & WHITNEY LLP

Ms. Mary MCAuliffe June 20, 2001 Page 2

Now that you have the supplemental information on the project, we hope you will be able to complete your internal review and approve this modification expeditiously. As we noted in our previous correspondence, Met Council believes that this change may be effected by written agreement of Met Council and the EPA without the need for Court involvement, though we would provide the Court a copy of any such agreement. I will follow up with a telephone call to discuss the next appropriate steps once you have had a chance to review the supplemental information with your technical staff.

Very truly yours,

Robert E. Cattanach

WW:djs Enclosure



CH2M HILL 1380 Corporate Center Curve Suite 200 Eagan, MN 55121-1200 Tel 651,688.8100

Fax 651,688,8844

May 31, 2001

Mr. Harold Voth Metropolitan Council Environmental Service Metro Plant Engineering 2450 Childs Road St. Paul, MN 55106

Subject: Replacement of Dry ESP with Fabric Filter

Dear Mr. Voth:

CH2M HILL has reviewed and concurs with the Von Roll recommendation to replace the dry electrostatic precipitator (ESP) with a fabric filter in the fluidized bed incinerator and air pollution control trains. The fabric filter technology would be an enhancement to the MCES voluntary mercury reduction program while providing better particulate removal capability.

Particulate Removal Performance

The fabric filter should result in better particulate removal efficiencies than the dry ESP because it is less sensitive to fluctuations in gas stream conditions, variations in particle size or variations in physical parameters, such as resistivity of the particulate matter. Performance data from both a fabric filter supplier and dry ESP supplier being considered for this project were evaluated. The collection efficiency versus particle diameter for each supplier's equipment is summarized as follows:

| | Collection Efficiency (%) | | | | |
|-----------------------------|---------------------------|---------------|--|--|--|
| Particle Diameter (microns) | Dry ESP | Fabric Filter | | | |
| 0.3 – 1 | 91.3 - 93 | >99 | | | |
| 1 - 3 | 93 - 99 | 100 | | | |
| 3 – 5 | >99 | 100 | | | |
| >5 | >99 | 100 | | | |

Mr. Harold Voth Page 2 May 31, 2001

Fabric filter removal efficiency below 0.3 microns is not reported because the fabric filter is not designed to provide significant removal of submicron particles. Particles below 0.3 microns approach the pore size opening of the fabric resulting in reduced collection efficiency. The downstream wet scrubber and wet ESP provided on the air pollution control trains are, however, designed to remove submicron particles.

Based on this data, the fabric filter offers superior performance for particles greater that 0.3 microns as compared to the dry ESP. The specified performance requirements for the air pollution control train include a maximum particulate matter emission rate of 0.1 lbs per dry ton solids incinerated. Von Roll will guarantee this performance for an air pollution control train that includes either the dry ESP or the fabric filter.

Enhanced Mercury Reduction

In addition to providing better particulate removal efficiency down to the 0.3-micron level, fabric filters provide a greater potential for increased mercury removal efficiency when combined with upstream carbon injection. Carbon injection followed by a dry ESP requires that mercury adsorption onto carbon particles occurs in a reaction chamber. The electrostatically charged carbon particles are then collected and removed in the dry ESP. In the fabric filter, however, mercury adsorption can occur in both the reaction chamber and on the fabric filter. A layer of carbon will develop on the fabric filter surface and improve the adsorption efficiency between the carbon and the mercury.

The advantages of the fabric filter for mercury control are discussed for municipal waste combustors in the EPA Mercury Study Report To Congress, Volume VIII: An Evaluation of Mercury Control Technologies and Costs (EPA-452/R-87-010), December 1997. The report states:

"With activated carbon injection, efficient distribution of the carbon in the flue gas is also important. The amount of carbon needed to achieve a specific level of mercury removal will vary depending on the fuel being burned, the amount of carbon inherent to the system and the type of particulate matter control device. At a given carbon feed rate, a fabric filter provides more mercury control than an ESP because of the additional mercury adsorption that occurs on the bags of the fabric filter (due to the increased gas contact time). Mercury is predominately removed upstream of an ESP-equipped facility where a nominal residence time of 1 second or less is available, limiting the capture. In addition, mercury is not effectively collected across the ESP further requiring substantially higher carbon feed rates than the fabric filter equipped facilities."

We believe carbon injection followed by a dry ESP will provide up to 70 percent mercury removal efficiency, whereas carbon injection followed by a fabric filter should be able to achieve up to 90 percent mercury removal.

Mr. Harold Voth Page 3 May 31, 2001

Fabric Filter Quality

The fabric filter material being considered for this project is a woven fiberglass material with a polytetrafluoroethylene (PTFE) finish. The proposed inlet operating temperature range to the fabric filter is 287°F to 350°F, which is below the 500°F maximum temperature rating of the fiberglass fabric material. The PTFE finish provides a slick coating on the filter to improve cleanability and reduce residual dust buildup on the fabric.

Cost

The cost of adding a fabric filter was evaluated and compared to the cost of adding a dry ESP to one air pollution control train. The cost estimate results are summarized as follows:

| | Cost | | | | |
|---------------------------------------|-------------|---------------|--|--|--|
| ltem | Dry ESP | Fabric Filter | | | |
| Equipment | \$595,000 | \$650,000 | | | |
| Mechanical Installation | \$135,000 | \$153,000 | | | |
| Electrical Installation | \$140,000 | \$93,000 | | | |
| Additional ID Fan Capacity | * | \$10,000 | | | |
| Additional Required Building Space | \$1,238,000 | \$1,238,000 | | | |
| Total | \$2,108,000 | \$2,144,000 | | | |

If you have any questions please feel free to contact us at (651) 688-8100.

Sincerely,

CH2M HILL

John Borghesi, P.E.

Project Engineer

Peter Burrowes, P. Eng.

Principal Technologist

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5

OFFICE OF REGIONAL COUNSEL 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

FACSIMILE TRANSMISSION

This facsimile is intended only for the use of the individual or entity to which it is addressed and contains information that is privileged, confidential, and exempt from disclosure. If the recipient of this facsimile is not the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this facsimile is strictly prohibited. If you have received this communication in error, please notify this office immediately by telephone and return the original facsimile to us at the above address by the U.S. Post Office. Thank you.

Date:

June 27, 2001

FAX Recipient:

Randy Stone, Esquire

DOJ

FAX Number:

(202) 616-6584

FAX Sender:

Mary McAuliffe

U.S. EPA, Region 5

My Phone:

(312) 886-6237

My FAX Number:

(312) 886-0747

Subject:

Met

Pages:

5 + cover

Message:

Randy,

From out of nowhere, we get this SEP stuff from Met.

Anyway, Met confirmed that they will be meeting with us in Chicago at 1pm on Monday, July 30th, in room 1712 of the Metcalfe Building. I feel weird about dragging them to Chicago if you are going to be on the phone from DC. Please let me know how travel \$\$ look and if the outlook is not rosy, maybe we should convert this to a teleconference. Thanks.

Confirmation Report

Page : 001

Date & Time: 06-27-01 11:02am

Line 1 : 312 886 7160

Machine ID: USEPA Region 5 ORC

| Nbr. | Job | Date | Time | Duration | pgs | To | Dept.nbr | Account | Comm. code | Status |
|------|-----|-------|---------|----------|-----|--------------|----------|---------|------------|--------|
| 352 | 269 | 06-27 | 11:00am | 01/39 | 006 | 912026166584 | | | EC 502 | OK |